About This Mac

Mac OS X

Version 10.3.9

Software Update...

Processor 450 MHz PowerPC G4

Memory 2 GB SDRAM

More Info...

TM & © Apple Computer, Inc. 1983-2004
All Rights Reserved.

System Profile

Dez Roth's Computer — 01/06/2014 11:49

Contents
- Hardware
  - Memory
  - PCI/AGP Cards
  - ATA
  - SCSI
  - USB
  - FireWire
  - AirPort Card
  - Modems
- Software
  - Applications
  - Extensions
- Network
- Logs

Card	Type	Bus	Slot
2 channel SATA	sata	PCI	SLOT-B
2 channel SATA	sata	PCI	SLOT-C
usb	usb	PCI	SLOT-D
usb	usb	PCI	SLOT-D
pcie55,2928		PCI	SLOT-D
ATY,RV280	display	AGP	SLOT-A
Display	display		
ATY,Bugsy_B			

2 channel SATA:

Name:	WiebeSATA3112
Type:	sata
Bus:	PCI
Slot:	SLOT-B
Vendor ID:	0x1095
Device ID:	0x3112
Subsystem Vendor ID:	0x1095
Subsystem ID:	0x3112
ROM Revision:	1.0
Revision ID:	0x0001

2 channel SATA:

Name:	WiebeSATA3112
Type:	sata
Bus:	PCI
Slot:	SLOT-C
Vendor ID:	0x1095
Device ID:	0x3112
Subsystem Vendor ID:	0x1095
Subsystem ID:	0x3112
ROM Revision:	1.0
Revision ID:	0x0001

HP w19ev : Info

ATI RADEON 9200

Info
Multimedia
Mac2TV™
Advanced
3D

Display Info | Profile | Support

Card#:	109-A27500-00
Card Model:	ATY,RV280
Vendor ID:	$1002 (4098)
ROM Name:	ATY,Bugsy_A
ROM#:	113-A27502-127
FCode Version:	1.94
NDRV Version:	1.1.0f59
VRAM Size:	128 MB