

P5E	Intel X38 + ICH9 Chipset	<ul style="list-style-type: none"> <li>Install Method: Kalyway 10.5.1 or iAtkos v1.0i</li> <li>BIOS version 0501, Rev. unknown</li> <li>IDE &amp; SATA works</li> <li>Kalyway:</li> <li>LAN working out of the box</li> <li>Audio works out of the box</li> <li>SATA fully working both AHCI and IDE mode</li> <li>iAtkos:</li> </ul>	EFI 8 + Vanilla kernel working	Yes & No, release dependent
P5K PRO	Intel P35 + ICH9 Chipset	<ul style="list-style-type: none"> <li>Install method: BrazilMac + EFI v8</li> <li>BIOS version 0501, Rev. unknown</li> <li>Audio working with ALC833 Taruga Patch 1.9</li> <li>Marvell LAN fully working</li> </ul>	EFI v8 working	Audio needs patching
P5KR	Intel P35 + ICH9R Chipset	<ul style="list-style-type: none"> <li>Install method: Kalyway 10.5.1</li> <li>Onboard audio working with <a href="#">[1]</a>  this ALC883installer</li> <li>LAN doesn't work</li> <li>IDE working fully</li> <li>SATA working fully</li> </ul>	EFI v8 working ; vanilla kernel working	Audio working with <a href="#">[2]</a>  this ALC883installer
P5W DH Deluxe	Intel 975X Express Chipset	<ul style="list-style-type: none"> <li>Install Method: Kalyway 10.5.1 or ToH or BrazilMac 10.5 + EFI + Software Update</li> <li>BIOS version 2403, Rev. unknown</li> <li>LAN working out of the box</li> <li>Audio works out of the box (Kalyway) or with kext from <a href="#">here</a> </li> <li>Realtek Wifi works out of the box with Kalyway included patch; furthermore, 10.4 drivers are available on Realtek website <a href="#">[3]</a> </li> <li>FireWire works</li> </ul>	EFI v8 + Vanilla kernel working (out of the box with Kalyway)	Yes (HD coax audio non functional)
P5B	Intel P965 + ICH8 Chipset	<ul style="list-style-type: none"> <li>Install method: iAtkos v1.0i or Kalyway 10.5.1</li> <li>BIOS version 1803, Rev. unknown</li> <li>iAtkos:</li> <li>Audio output works out of the box, input not tested</li> <li>LAN works out of the box</li> <li>IDE non installable, works as storage</li> <li>SATA ports 1-2 should be set as AHCI</li> <li>SATA ports 3-4 should be set as SATA (IDE default)</li> <li>USB ports 7-10 does not work</li> <li>Kalyway:</li> <li>Audio output not working, needs azalia.pkg from 10.4.8. Or delete AppleHDA.kext and ALCInject.kext then edit dev id in AppleAzaliaAudio.kext</li> <li>LAN works out of the box</li> <li>All 4 SATA port ok under IDE mode</li> <li>Jmicron ok in SATA or AHCI but may need dev id edit in the JMicroATA.kext</li> <li>USB ports works out of the box</li> <li>PCI ports works out of the box</li> </ul>	EFI v8 + Vanilla kernel working	Yes; Some limitations present
P5LD2	Intel 945P	<ul style="list-style-type: none"> <li>Install Method: Kalyway</li> <li>Version 2, BIOS version 1804</li> <li>Audio works with AppleHDA patcher</li> <li>LAN works</li> <li>BIOS needing tweaking to stop constant reboot</li> <li>SATA works</li> </ul>	PC-EFI	Audio needs patch
P5LD2-VM	Intel 945G + ICH7	<ul style="list-style-type: none"> <li>Install method: ToH RC2</li> <li>ALC882 audio works with Taruga's ALC Patch</li> <li>LAN works out of the box</li> </ul>	PC-EFI & Vanilla Kernel	Audio needs patch
P5L-VM	Intel 945G	<ul style="list-style-type: none"> <li>Install Method: iATKOS</li> <li>Analog in/out and spdif out works with AppleHDA patcher</li> <li>LAN doesn't work</li> </ul>	PC-EFI works, Vanilla doesn't	Audio needs patching
P5L-MX	Intel 945G	<ul style="list-style-type: none"> <li>Install Method: iAtkos v1.0i</li> <li>Audio works out of the box</li> <li>LAN wasn't tested</li> <li>SATA &amp; IDE works</li> </ul>	EFI v8 + Vanilla kernel working	Yes
P5GC-MX/1333	Intel 945GC(A2) + ICH7 Chipset	<ul style="list-style-type: none"> <li>Install method: Kalyway 10.5.1 or Brazil</li> <li>Sound ALC883 works with Audio Out/in with Taruga's HDAPatcher</li> <li>LAN doesn't work</li> <li>IDE working fully</li> <li>SATA working fully</li> </ul>	EFI v8: Unknown; vanilla kernel sends no power to the PS/2 ports	Audio needs patching with Taruga's HDAPatcher
Asus P5GC-MX	Intel 945GC + ICH7 Chipset	<ul style="list-style-type: none"> <li>HD fresh install with GUID using Disc Utility</li> <li>iATKOS v1.0i SSE3 with vanilla kernel 10.5.1</li> <li>Used PC_EFIv8 for GUID booting</li> <li>Onboard LAN doesn't work</li> </ul>	YES	Audio needs patching HDAPatcher ALC883

P4C800-E Deluxe	Intel 875P	<ul style="list-style-type: none"> <li>■ Install Method: Kalyway 10.5.1</li> <li>■ Audio &amp; LAN work out of the box</li> <li>■ SATA/IDE works</li> </ul>	EFI v8	Yes
P4B	Intel 845 (Brookdale)	<ul style="list-style-type: none"> <li>■ Install Method: ToH Leopard 10.5 + 10.5.1 Update with kernel removed</li> <li>■ Audio work out of the box</li> <li>■ IDE works</li> </ul>	MBR	Yes