

HDDScan S.M.A.R.T. Report

Model: Hitachi HTS545032B9A302

Firmware: PB3AC60Y

Serial: 110131PBS3004THS0N2S

LBA: 625142448

Report By: HDDScan for Windows version 3.3

Report Date: 31/07/2012 2:54:54 p.m.

	Num	Attribute Name	Value	Worst	Raw(hex)	Threshold
	001	Raw Read Error Rate	086	086	000000006A-0000	062
	002	Throughput performance	100	100	0000000000-0000	040
	003	Spin Up Time	149	149	0000150000-0002	033
	004	Start/Stop Count	099	099	0000000000-06B7	000
	005	Reallocation Sector Count	100	100	0000000000-0004	005
	007	Seek Error Rate	100	100	0000000000-0000	067
	008	Seek time Performance	100	100	0000000000-0000	040
	009	Power-On Hours Count	093	093	0000000000-0D7F	000
	010	Spin Retry Count	100	100	0000000000-0000	060
	012	Device Power Cycle Count	099	099	0000000000-0678	000
	160	Free-fall Sensor Self Test Result	100	100	0000000000-0000	000
	191	G-sense Rate/Servo tracking	100	100	000C9C0000-0000	000
	192	Emergency Retract Count	100	100	0000180000-0072	000
	193	Load/unload Cycle Count	097	097	0000000000-94F0	000
	194	HDA Temperature	220	220	25 C	000
	194	HDA Temperature Maximum	220	220	48 C	000
	194	HDA Temperature Minimum	220	220	03 C	000
	195	Hardware ECC Recovered	100	100	0000000000-0000	000
	196	Reallocation Event Count	100	100	0000000000-0004	000
	197	Current Pending Errors Count	100	100	0000000000-0018	000
	198	Uncorrectable Errors Count	100	100	0000000000-0000	000
	199	UltraDMA CRC Errors	200	200	0000000000-0000	000
	223	Load Retry Count	100	100	0000000000-0000	000
	254	G-shock/Free-fall Event Count	076	076	0000010000-18E1	000

Mike Lovell

General Manager

Nzlaptops (Laptec Ltd)

09 577 3338 x2

www.nzlaptops.co.nz

