

Interval Since Last Panic Report: 21838 sec
Panics Since Last Report: 1
Anonymous UUID: 8E02B811-CC5E-E835-ECB6-8AD93AE683FE

Sat Oct 12 10:56:13 2013

panic(cpu 0 caller 0xfffff7f9e26cf1a): "GPU Panic: [<None>] 3 3 7f 0 0 0 0 3 : NVRM[0/1:0:0]: Read Error 0x00000100: CFG 0xffffffff 0xffffffff 0xffffffff, BAR0 0xd2000000 0xffffffff810cf8c000 0x0a5480a2, D0, P2/4\n"/SourceCache/AppleGraphicsControl/AppleGraphicsControl-3.4.5/src/AppleMuxControl/kext/GPUPanic.cpp:127

Backtrace (CPU 0), Frame : Return Address

0xfffff810cb7b710 : 0xfffff801c01d636
0xfffff810cb7b780 : 0xfffff7f9e26cf1a
0xfffff810cb7b850 : 0xfffff7f9c77026c
0xfffff810cb7b910 : 0xfffff7f9c8431f6
0xfffff810cb7b950 : 0xfffff7f9c843254
0xfffff810cb7b9c0 : 0xfffff7f9cb08278
0xfffff810cb7baf0 : 0xfffff7f9c86bad1
0xfffff810cb7bb10 : 0xfffff7f9c77703f
0xfffff810cb7bbc0 : 0xfffff7f9c774ad6
0xfffff810cb7bdc0 : 0xfffff7f9c775b41
0xfffff810cb7bea0 : 0xfffff7f9c71180a
0xfffff810cb7bef0 : 0xfffff7f9e22e838
0xfffff810cb7bf40 : 0xfffff7f9e22d783
0xfffff810cb7bf60 : 0xfffff801c03e26e
0xfffff810cb7bf80 : 0xfffff801c0b3257

Kernel Extensions in backtrace:

com.apple.NVDAResman(8.1.6)[EA4F9902-5AAE-3F1D-A846-3796221C8C91]@0xfffff7f9c70f000->0xfffff7f9c9b1fff
dependency: com.apple.iokit.IOPCIFamily(2.8)[2FAEA49C-EA4C-39C6-9203-FC022277A43C]@0xfffff7f9c675000
dependency: com.apple.iokit.IONDRVSupport(2.3.7)[F16E015E-1ABE-3C40-AC71-BC54F4BE442E]@0xfffff7f9c6fb000
dependency: com.apple.iokit.IOGraphicsFamily(2.3.7)[9928306E-3508-3DBC-80A4-D8F1D87650D7]@0xfffff7f9c6b8000
com.apple.nvidia.nv50hal(8.1.6)
[3455BCFE-565A-3FE5-9F0B-855BCB6CC9B3]@0xfffff7f9c9bd000->0xfffff7f9cc90fff
dependency: com.apple.NVDAResman(8.1.6)[EA4F9902-5AAE-3F1D-A846-3796221C8C91]@0xfffff7f9c70f000
dependency: com.apple.iokit.IOPCIFamily(2.8)[2FAEA49C-EA4C-39C6-9203-FC022277A43C]@0xfffff7f9c675000
com.apple.driver.AppleMuxControl(3.4.5)[49FEF732-D7A3-327B-A7AA-6AC5A6E3DCFF]@0xfffff7f9e25f000->0xfffff7f9e271fff
dependency: com.apple.driver.AppleBacklightExpert(1.0.4)
[B5B1F368-132E-3509-9ED5-93270E3ABBDD]@0xfffff7f9e25a000
dependency: com.apple.iokit.IOPCIFamily(2.8)[2FAEA49C-EA4C-39C6-9203-FC022277A43C]@0xfffff7f9c675000
dependency: com.apple.driver.AppleGraphicsControl(3.4.5)[4A2C8548-7EF1-38A9-8817-E8CB34B8DCA6]@0xfffff7f9e246000
dependency: com.apple.iokit.IOACPIFamily(1.4)[A35915E8-C1B0-3C0F-81DF-5515BC9002FC]@0xfffff7f9c5f3000
dependency: com.apple.iokit.IONDRVSupport(2.3.7)[F16E015E-1ABE-3C40-AC71-BC54F4BE442E]@0xfffff7f9c6fb000
dependency: com.apple.iokit.IOGraphicsFamily(2.3.7)[9928306E-3508-3DBC-80A4-D8F1D87650D7]@0xfffff7f9c6b8000
com.apple.driver.AGPM(100.13.12)[40BECF44-B2F1-3933-8074-AD07B38CA43A]@0xfffff7f9e22c000->0xfffff7f9e23dfff
dependency: com.apple.iokit.IOPCIFamily(2.8)[2FAEA49C-EA4C-39C6-9203-FC022277A43C]@0xfffff7f9c675000
dependency: com.apple.driver.IOPPlatformPluginFamily(5.4.1d11)[D57AB2EB-A2D1-3002-BDAA-E61E23A9D8F7]@0xfffff7f9d129000

dependency: com.apple.iokit.IONDRVSupport(2.3.7)[F16E015E-1ABE-3C40-AC71-BC54F4BE442E]@0xffffffff7f9c6fb000

dependency: com.apple.iokit.IOGraphicsFamily(2.3.7)[9928306E-3508-3DBC-80A4-D8F1D87650D7]@0xffffffff7f9c6b8000

BSD process name corresponding to current thread: kernel_task

Mac OS version:
12F37

Kernel version:
Darwin Kernel Version 12.5.0: Mon Jul 29 16:33:49 PDT 2013; root:xnu-2050.48.11~1/
RELEASE_X86_64
Kernel UUID: B1B58405-A2B2-3C44-B25D-495053D52AB5
Kernel slide: 0x000000001be00000
Kernel text base: 0xffffffff801c000000
System model name: MacBookPro6,2 (Mac-F22586C8)

System uptime in nanoseconds: 6028799914548
last loaded kext at 245664302988: com.apple.filesystems.msdosfs
1.8.1 (addr 0xffffffff7f9e370000, size 65536)
last unloaded kext at 305930373247: com.apple.filesystems.msdosfs
1.8.1 (addr 0xffffffff7f9e370000, size 57344)
loaded kexts:
com.apple.driver.AppleHWSensor 1.9.5d0
com.apple.driver.AudioAUUC 1.60
com.apple.filesystems.autofs 3.0
com.apple.driver.AGPM 100.13.12
com.apple.iokit.IOBluetoothSerialManager 4.1.7f2
com.apple.driver.AppleMikeyHIDDriver 124
com.apple.iokit.IOUserEthernet 1.0.0d1
com.apple.GeForce 8.1.6
com.apple.driver.AppleMikeyDriver 2.4.7fc2
com.apple.driver.AppleUpstreamUserClient 3.5.12
com.apple.driver.AppleIntelHDGraphics 8.1.6
com.apple.Dont_Steal_Mac_OS_X 7.0.0
com.apple.driver.AppleMCCSControl 1.1.11
com.apple.iokit.BroadcomBluetoothHostControllerUSBTransport
4.1.7f2
com.apple.driver.AppleMuxControl 3.4.5
com.apple.driver.ApplePolicyControl 3.4.5
com.apple.driver.AppleSMBusPCI 1.0.11d1
com.apple.driver.AppleLPC 1.6.3
com.apple.driver.AppleHDA 2.4.7fc2
com.apple.driver.AppleSMCPDRC 1.0.0
com.apple.driver.AppleSMCLMU 2.0.3d0
com.apple.driver.ACPI_SMC_PlatformPlugin 1.0.0
com.apple.driver.AppleIntelHDGraphicsFB 8.1.6
com.apple.driver.SMCMotionSensor 3.0.3d1
com.apple.driver.AppleUSBTCTButtons 237.1
com.apple.driver.AppleUSBTCTKeyboard 237.1
com.apple.driver.AppleIRController 320.15
com.apple.driver.AppleUSBCardReader 3.3.1
com.apple.AppleFSCompression.AppleFSCompressionTypeDataless
1.0.0d1
com.apple.AppleFSCompression.AppleFSCompressionTypeZlib
1.0.0d1
com.apple.BootCache 34
com.apple.driver.XsanFilter 404
com.apple.iokit.IOAHCIBlockStorage 2.3.5

com.apple.driver.AppleFWOHCI 4.9.9
com.apple.driver.AppleUSBHub623.4.4
com.apple.driver.AirPort.Brcm4331 615.20.17
com.apple.driver.AppleAHCIPort 2.6.6
com.apple.iokit.AppleBCM5701Ethernet 3.6.2b4
com.apple.driver.AppleUSBEHCI 621.4.6
com.apple.driver.AppleSmartBatteryManager 161.0.0
com.apple.driver.AppleRTC 1.5
com.apple.driver.AppleACPIButtons 1.8
com.apple.driver.AppleHPET 1.8
com.apple.driver.AppleSMBIOS 1.9
com.apple.driver.AppleACPIEC 1.8
com.apple.driver.AppleAPIC 1.7
com.apple.driver.AppleIntelCPUPowerManagementClient 214.0.0
com.apple.nke.applicationfirewall 4.0.39
com.apple.security.quarantine 2.1
com.apple.driver.AppleIntelCPUPowerManagement 214.0.0
com.apple.kext.triggers 1.0
com.apple.iokit.IOSerialFamily 10.0.6
com.apple.iokit.IOSurface 86.0.4
com.apple.iokit.IOBluetoothFamily 4.1.7f2
com.apple.driver.AppleSMBusController 1.0.11d1
com.apple.iokit.IOBluetoothHostControllerUSBTransport 4.1.7f2
com.apple.driver.AppleBacklightExpert 1.0.4
com.apple.driver.AppleGraphicsControl 3.4.5
com.apple.driver.DspFuncLib 2.4.7fc2
com.apple.iokit.IOAudioFamily 1.9.2fc7
com.apple.kext.OSvKernDSPLib 1.12
com.apple.nvidia.nv50hal 8.1.6
com.apple.NVDAResman 8.1.6
com.apple.iokit.IOFireWireIP 2.2.5
com.apple.driver.AppleHDAController 2.4.7fc2
com.apple.iokit.IOHDAFamily 2.4.7fc2
com.apple.driver.IOPPlatformPluginLegacy 1.0.0
com.apple.driver.IOPPlatformPluginFamily 5.4.1d11
com.apple.iokit.IONDRVSupport 2.3.7
com.apple.iokit.IOGraphicsFamily 2.3.7
com.apple.driver.AppleSMC 3.1.5d4
com.apple.driver.AppleUSBMultitouch 237.3
com.apple.iokit.IOUSBHIDDriver 623.4.0
com.apple.iokit.IOCSIBlockCommandsDevice 3.5.6
com.apple.iokit.IOUSBMassStorageClass 3.5.2
com.apple.iokit.IOSCSIArchitectureModelFamily 3.5.6
com.apple.driver.AppleUSBMergeNub 621.4.6
com.apple.driver.AppleUSBComposite 621.4.0
com.apple.iokit.IOFireWireFamily 4.5.5
com.apple.iokit.IO80211Family 530.5
com.apple.iokit.IOUSBUserClient 630.4.4
com.apple.iokit.IOAHCIFamily 2.5.1
com.apple.iokit.IOEthernetAVBController 1.0.2b1
com.apple.iokit.IONetworkingFamily 3.0
com.apple.iokit.IOUSBFamily 630.4.5
com.apple.driver.AppleEFINVRAM 2.0
com.apple.driver.AppleEFIRuntime 2.0
com.apple.iokit.IOHIDFamily 1.8.1
com.apple.iokit.IOSMBusFamily 1.1
com.apple.security.sandbox 220.3
com.apple.kext.AppleMatch 1.0.0d1
com.apple.security.TMSafetyNet 7
com.apple.driver.DiskImages 345

com.apple.iokit.IOStorageFamily 1.8
com.apple.driver.AppleKeyStore 28.21
com.apple.driver.AppleACPIPlatform 1.8
com.apple.iokit.IOPCIFamily 2.8
com.apple.iokit.IOACPIFamily 1.4
com.apple.kec.corecrypto 1.0
Model: MacBookPro6,2, BootROM MBP61.0057.B0F, 2 processors, Intel Core i5, 2.53 GHz, 8 GB,
SMC 1.58f17
Graphics: Intel HD Graphics, Intel HD Graphics, Built-In, 288 MB
Graphics: NVIDIA GeForce GT 330M, NVIDIA GeForce GT 330M, PCIe, 256 MB
Memory Module: BANK 0/DIMM0, 4 GB, DDR3, 1067 MHz, 0x802C,
0x31364A53463531323634485A2D3147344431
Memory Module: BANK 1/DIMM0, 4 GB, DDR3, 1067 MHz, 0x802C,
0x31364A53463531323634485A2D3147344431
AirPort: spairport_wireless_card_type_airport_extreme (0x14E4, 0x93), Broadcom BCM43xx 1.0
(5.106.98.100.17)
Bluetooth: Version 4.1.7f2 12718, 3 service, 13 devices, 3 incoming serial ports
Network Service: Wi-Fi, AirPort, en1
Serial ATA Device: Hitachi HTS545050B9SA02, 500.11 GB
Serial ATA Device: Samsung SSD 840 Series, 500.11 GB
USB Device: hub_device, 0x0424 (SMSC), 0x2514, 0xfa100000 / 2
USB Device: Apple Internal Keyboard / Trackpad, apple_vendor_id, 0x0237, 0xfa120000 / 5
USB Device: BRCM2070 Hub, 0x0a5c (Broadcom Corp.), 0x4500, 0xfa110000 / 4
USB Device: Bluetooth USB Host Controller, apple_vendor_id, 0x8218, 0xfa113000 / 6
USB Device: Internal Memory Card Reader, apple_vendor_id, 0x8403, 0xfa130000 / 3
USB Device: hub_device, 0x0424 (SMSC), 0x2514, 0xfd100000 / 2
USB Device: IR Receiver, apple_vendor_id, 0x8242, 0xfd120000 / 4
USB Device: Built-in iSight, apple_vendor_id, 0x8507, 0xfd110000 / 3